



## 2010 DEMO BRAND DEMO MODEL

Report verified by JP Center

**B**

Condition

### VEHICLE DETAILS

Lot number

**12345**

Auction

**Demo Auction**

Auction date

**2022-01-15**

Chassis ID

**ABC123X**

Vendor

**DEMO BRAND**

Model

**DEMO MODEL**

Mileage

**50,000 km**

Engine CC

**2000**

Year

**2010**

Grade

**DX**

Inspection

**2023.12**

Equipment

**AC**

Transmission

**Automatic**

Awd

**1**

Start price

**100,000 YEN**

Finish price

**200,000 YEN**

Color

**BLACK**

Condition

**B**


Status

**sold**

Chassis

**ABC123X-987654**

## CONDITION SHEETS & PHOTOS



## CONDITION LIST EXPLANATION

**A1:** Small Scratch

**A2:** Scratch

**A3:** Big Scratch

**B:** Dent with scratch

**B1:** Distortion on (radiator) core support or back panel (approximately size of a thumb)

**B2:** Big Distortion on (radiator) core support or back panel

**B1-B4:** Large dents

**C1:** Corrosion

**C2:** Heavy Corrosion

**AU2:** Dent and Scratch ( Medium)

**E1:** Few Dimples

**E2:** Several Dimples

**E3:** Many Dimples

**G:** Stone chips in glass

**H:** Paint faded or (Thumb size hole from rust, corrosion or rotting)

**P:** Paint damaged marked

**S1:** Rust

**S2:** Heavy Rust

**U1:** Small Dent

**U2:** Dent

**U3:** Big Dent

**Y1:** Small Hole or Crack

**Y2:** Hole or Crack

**Y3:** Big Hole or Crack

**X1:** Small Crack on Windshield (approximately 1cm)

**R:** Repaired Crack on Windshield

**RX:** Repaired Crack on Windshield (needs to be replaced)

**X:** Needs to be replaced or crack on glass

**XX:** Replaced

**W1:** Repair Mark/Wave (hardly detectable)

**W2:** Repair Mark/Wave

**W3:** Obvious Repair Mark/Wave (needs to be repainted)

# AUCTION GRADE EXPLANATION

**6/S** New car

**5** Used but appears as new

**4.5** Very clean with only minor pin dents & scratches

**4** Good condition with normal wear & tear

**3.5** Numerous condition faults / possible minor repair

**3** Poor condition / noticeable dents & damage / rust / past repair

**2** Very poor condition / water damaged

**0** Repaired

**R Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)**


**RA Accident repaired, been in crash, parts replaced, generally small damages.**

**\*\*\* Ungraded (existing fault / damage)**

**A - D Body / interior condition ( A – as new, B – very clean, C – average, D – poor)**

**E** – The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty

**1** Modified (usually performance parts)





**JP AS**

© 2025 JPAS. All rights reserved.

<https://jpauctionsheet.com>